

WINPLUS

GPS Tracker Calibration



- Step 1: Turn unit on and make sure it's in Navigation Mode
- Step 2: Press and hold the up & down arrows together for about 5 seconds
- Step 3: This will bring up the "Dist. Unit" setting
- Step 4: Press the Up or Down arrows to select the proper distance unit (Mile, KM, N. Mile)
- Step 5: Press the Set button to enter the "Interval Nav" settings
- Step 6: Press the Up or Down arrows to set intervals for recording
- Step 7: Press the Set button to enter "LT Adjust" settings
- Step 8: In this setting, you must enter the correct number for your specific time zone*
- Step 9: Press the Set button to enter the "Calibrate Compass" settings
- Step 10: Press the Info button to begin calibration
- Step 11: Walk around in a circle 2-3 times
- Step 12: Press the Set button
- Step 13: Set the backlight to your preferred setting
- Step 14: Press the Info button to exit calibration mode

*This information can be found on page 14 of the instruction booklet

**It is highly recommended to calibrate the device outdoors to get accurate results